

US 360 Arterial Management Plan Corridor Recommendations Sheet 17

Intersections and Median Crossovers

I.43 US 360 at median opening west of Circle **Drive (MM 111.29)**

• Add deer crossing sign

I.44 US 360 at median opening west of Circle **Drive (MM 111.48)**

- · Convert to directional median opening
- Extend all turn lanes to meet standard
- Systematic safety improvements (Improve signing and marking)
- Consolidate driveways

I.45 US 360 at Circle Drive

Close median opening

I.46 US 360 at median opening east of Circle **Drive (MM 112.02)**

· Close median opening

I.47 US 360 at median opening east of Circle **Drive (MM 112.178)**

- Extend all turn lanes to meet standard
- Systematic safety improvements (Improve signing and marking)

Roadway

R.4 US 360 from MM 111.48 to MM 111.671

Consolidate driveways



1.#

Intersection Number


Number

Existing Deficiency



Geometry











Recommendation







US 360 Arterial Management Plan Corridor Recommendations Sheet 20

Intersections and Median Crossovers

I.48 US 360 at Median Opening at MM 114.36

Close median opening

Roadway

R.5 US 360 from MM 112.56 to east of Doss Road

- Improve shoulders
- Install rumble strips

Legend | Chesterfield County Roadway, Intersection, and Median Crossover Recommendations

I.#

(38)

(307)

Legend

Figure Area

US 360 Study Corridor

Intersection Number



Roadway Segment Number





Access Management











