

Intersections and Median Crossovers

I.66 US 360 at median opening east of **Hampton Farms Drive (MM 121.2)**

- · Convert to directional median opening
- · Extend all turn lanes to meet standard
- Improve signing and marking to meet systematic safety improvement standards



1.#

38

(307)

Legend

Figure Area

US 360 Study Corridor



Number









Intersections and Median Crossovers

I.67 US 360 at Otterdale Road

• Recommendation dependent on Otterdale Road preferred alternative

I.68 US 360 at Fox Club Parkway/Hampton **Park Drive**

• Recommendation dependent on Fox Club Parkway/Hampton Park Drive preferred alternative



Recommendation

1.#

CHESTERFIELD COUNTY

Legend

Figure Area

US 360 Study Corridor

38

(307)

Intersection Number



Roadway Segment Number



Geometry

Access Management



Traffic Operations





Existing Deficiency



Intersections and Median Crossovers

I.69 US 360 at Cosby Road

• Recommendation dependent on Fox Club Parkway preferred alternative

I.70 US 360 at Woodlake Village Parkway

• Recommendation dependent on Woodlake Village Parkway preferred alternative

I.71 US 360 at Ashlake Parkway

Recommendation dependent on Ashlake Parkway preferred alternative



Legend | Chesterfield County Roadway, Intersection, and Median Crossover Recommendations

1.#

Intersection



Geometry









Number

Roadway Segment Number

Access Management



Intersections and Median Crossovers

I.72. US 360 at Hancock Village Drive

• Recommendation dependent on Hancock Village Drive preferred alternative

I.73. US 360 at Winterpock Road

Recommendation dependent on Winterpock Road preferred alternative

I.74. US 360 at Southshore Drive

Recommendation dependent on Winterpock Road preferred alternative



1.#

38

(307)

Legend

Figure Area

US 360 Study Corridor

Intersection Number



Roadway Segment Number



Access Management







