









## **Route 58 Arterial Management Plan** Figure 5 Intersection #14: US 58 and Virginia Ave

**Recommendation:** Reconfigure main intersection of US 58 and Virginia Ave to Continuous Green-T (CGT). Reconstruct existing turn-lanes on US 58 to VDOT Design Standards. Improvements are required at Intersection 15, Noblin Farm Rd and US 58.

ROW Impacts: All improvements are within the ROW

Improvement Type: Safety, Travel Time Preservation

## **Traffic Operations & Safety:**

Traffic Operations Reduced delay times for vehicles traveling eastbound on US 58 from Virginia Ave

Safety

Reduced conflict points where vehicles cross paths. Reduced risk of angle crashes from Virginia Ave onto US 58

Cost: \$1.1M to \$1.4M

**Standard Movements** 











