





US 17/360 (TAPPAHANNOCK BOULEVARD/CHURCH LANE) CORRIDOR STUDY

Public Meeting

October 14, 2021



GoToWebinar Controls

US 17/360 Corridor Study Public Meeting

Add to Calendar

1. Click the link to join the webinar at the specified time and date:

Thu, Oct 14, 2021 6:30 PM - 8:30 PM EDT

Join Webinar

Note: This link should not be shared with others; it is unique to you.

Before joining, be sure to check system requirements to avoid any connection issues.

2. Choose one of the following audio options:

TO USE YOUR COMPUTER'S AUDIO:

When the webinar begins, you will be connected to audio using your computer's microphone and speakers (VoIP). A headset is recommended.

--OR--


TO USE YOUR TELEPHONE:

If you prefer to use your phone, you must select "Use Telephone" after joining the webinar and call in using the numbers below.

United States: +1 (562) 247-8422

Access Code: 415-322-107


Audio PIN: Shown after joining the webinar





PRESENTATION OUTLINE

- Why is VDOT studying US 17/360?
- What are the issues?
- What are the possible solutions?
- How would the recommendations be funded?
- What are the next steps?






WHY IS VDOT STUDYING US 17/360 IN TAPPAHANNOCK?

The US 17/360 Corridor Study is a STARS project funded by VDOT in partnership with Essex County, the Town of Tappahannock, and the Middle Peninsula Planning District Commission.



US 17/360 STUDY CORRIDOR

- Airport Road to Lagrange Industrial Drive
- 3.5 miles long
- 5 intersections with Potential for Safety Improvements (PSI)
- 9 signalized intersections
- 11 unsignalized intersections
- Access Spacing Deficiencies




WHAT ARE THE ISSUES?

Issues have been identified with a combination of data and survey responses.

HIGH CRASH LOCATIONS

- Heat Map
- Potential for Safety Improvements (PSI): Locations where the crash frequency is greater than would be expected








METROQUEST SURVEY RESULTS

- May 7-June 42021
- >1,100 participants






METROQUEST SURVEY RESULTS: MAY 7- JUNE 4

Congestion

Where was US 17/360 typically congested before COVID? (check all that apply)



Safety

What safety issues did you experience on US 17/360 before COVID? (check all that apply)

24%

9%

11%


18%

9%

8%

10%

Speeding



■ Aggressive driving




- Sudden stops and rearend crashes
- Roadside hazards (e.g. utility poles)
- Road maintenance issues (potholes)
- Lack of clear signs or markings
- Unsignalized intersections
- Other



METROQUEST SURVEY RESULTS: MAY 7- JUNE 4

Access


What are the issues with driveways and entrances? (check all that apply)



Multimodal


What improvements are needed on US 17/360 for walking and bicycling? (check all that apply)

What mode of transit is needed on US 17/360? (check all that apply)






METROQUEST SURVEY RESULTS: MAP EXERCISE




Privacy - About MetroQuest







METROQUEST SURVEY RESULTS: MAP EXERCISE




METROQUEST SURVEY RESULTS: DEMOGRAPHICS




Do you live or work near US 17/360?



How did you find out about this






What is your age group?

■ Hispanic/Latino

Other

85%





SUMMARY OF ISSUES

- Crash clusters reveal a need for improvements at intersections
- Access spacing deficiencies create high number of conflict points and crash potential
- Congestion in Downtown Tappahannock
- Heavy truck traffic
- Narrow travel lanes
- Infrequent pedestrian crossings and sidewalk gaps
- Survey responses consistent with crash data and findings from analysis of existing traffic conditions









What are the Possible Solutions?



Possible Solutions

Downtown Tappahannock


- One-Way Pairs
- Partial Quadrant

US 17/360 at Brays Fork

- Continuous Green-T
- Roundabout

South of Hoskins Creek

- Median Modifications
- Pedestrian Improvements
- Access Modifications





Possible Solutions: Downtown Tappahannock




DOWNTOWN TAPPAHANNOCK ISSUES TO ADDRESS

- High crash frequency
 - Queen Street/Church Lane
 - Queen Street/Cross Street
 - Church Lane/Duke Street
- Congestion
- Heavy truck traffic
- Narrow travel lanes and sidewalks



CONGESTION

- Most significant at QueenStreet/Church Lane intersection
- Back-ups extend through adjacent intersections





DOWNTOWN TAPPAHANNOCK SOLUTIONS CONSIDERED

- Conventional Turn Lane Improvements
- Road Diet: One lane per direction
- Road Diet: Two lanes northbound, one lane southbound
- Quadrant Roadways
 - Southeast area: 3 options
 - Northeast area
 - Cross Street
 - Water Lane
- One-Way Pairs
 - Cross Street
 - Water Lane




DOWNTOWN TAPPAHANNOCK ONE-WAY PAIRS

- One-way streets in 2-block downtown core area
 - Church Lane southbound
 - Cross Street northbound
 - Queen Street westbound
 - Duke Street eastbound
- Moves traffic signal on Queen Street from Church Lane to Cross Street
- Removes traffic signal at Prince Street
- Wider sidewalks and wider travel lanes on Church Lane
- Removes most on-street parking on Cross Street
- Reduces travel times by 10-16 seconds, 9-14% reduction
- Reduces conflict points at:
 - Church Lane & Queen Street
 - Church Lane & Duke Street
 - Queen Street & Cross Street



DOWNTOWN TAPPAHANNOCK PARTIAL QUADRANT

- Church Lane becomes three lanes:
 - 1 northbound lane
 - 2 southbound lanes
- Vehicles from the south headed over the bridge turn right at Duke Street
- Wider sidewalks and wider travel lanes on Church Lane
- Reduces travel times by 15-20 seconds, 20% reduction
- Reduces conflict points at Church Lane/Queen Street intersection



Possible Solutions: Brays Fork




US 17/360 AT BRAYS FORK ISSUES TO ADDRESS

- Access to the hospital
- Closely spaced intersections
- Unusual geometry



US 17/360 AT BRAYS FORK CONTINUOUS GREEN-T


- Improves access to the hospital
- Reduces travel times by 18-22 seconds, 70% reduction
- Reduces conflict points at Berry Hill Road/US 17 intersection





US 17/360 AT BRAYS FORK ROUNDABOUT

- Improves access to the hospital
- Reduces travel times by 19-23 seconds, 76% reduction
- Reduces conflict points at Berry Hill Road/US 17 intersection
- Roundabouts generally reduce crashes by 50% compared to traffic signals





POSSIBLE SOLUTIONS: SOUTH OF HOSKINS CREEK



SOUTH OF HOSKINS CREEK - RICHMOND BEACH ROAD TO WHITE OAK DRIVE

ISSUES TO ADDRESS


- High crash frequency
 - Ball Street & Tappahannock Boulevard
 - Winston Road & Tappahannock Boulevard
- Closely spaced access points
- Lack of pedestrian facilities





Types of Access Points


- The number of conflict points represents the different ways a crash could occur.
- Fewer conflict points mean there is less potential for crashes to occur.
- A typical four-leg intersection has 32 conflict points.
- Turn restrictions reduce the number of conflict points and crash potential.





MINIMUM ACCESS SPACING STANDARDS

for US 17/360 south of Hoskins Creek*




*Access spacing standards shown are for principal arterials with 35 to 45 mph posted speed limits. US 17/360 north of Hoskins Creek is 25 mph with different access spacing standards.



ACCESS SPACING DEFICIENCIES ON US 17/360

Median openings and entrances are spaced too closely together.









Spacing between Partial Access Entrance and Any Entrance, Intersection or Median Crossover (250' where 25mph, 305' where 35 or 45mph)



ACCESS SPACING DEFICIENCIES ON US 17/360

Median openings and entrances are spaced too closely together.







Spacing between Signalized Intersection and Signalized Intersection (1,050' where 25mph, 1,320' where 35 or 45mph)

Spacing between Unsignalized Intersection/Full Median Crossover and Signalized Intersection/Unsignalized Intersection/Full Median Crossover (880' where 25mph, 1,050' where 35 or 45mpl

pacing between Full Access Entrance or Directional Median and Any Intersection, Full Access Entrance or Median Crossover (440' where 25mph, 565' where 35 or 45mph)

Spacing between Partial Access Entrance and Any Entrance, Intersection or Median Crossover (250' where 25mph, 305' where 35 or 45mph)



ACCESS SPACING DEFICIENCIES ON US 17/360

Median openings and entrances are spaced too closely together.





Deficient Length






Spacing between Partial Access Entrance and Any Entrance, Intersection or Median Crossover (250' where 25mph, 305' where 35 or 45mph)



South of Hoskins Creek: Reduced Conflict Intersection

- Side street movements begin with right turn
- Improve safety by reducing conflict points
- Recently installed at Winston Road






RELATIONSHIP BETWEEN ACCESS AND SAFETY

- Crash rates increase as the number of access points increase
- Richmond Beach Road to White Oak Drive 3.25 signals per mile

ESTIMATED CRASH RATES BY ACCESS DENSITY; URBAN AND SUBURBAN AREAS



©Transportation Research Board.




SOUTH OF HOSKINS CREEK





SOUTH OF HOSKINS CREEK





How would the recommended PROJECTS BE FUNDED?





FUNDING PROGRAMS











WHAT ARE THE NEXT STEPS?





NEXT STEPS

- Ask questions of the project team using the chat
- Tell us your thoughts at <u>fred.comments@vdot.virginia.gov</u>
- Take the MetroQuest survey at http://metroquestsurvey.com/w4e0m
- For more information contact:

Linda LaSut
VDOT Fredericksburg District
Assistant District Planner
linda.lasut@vdot.virginia.gov
540-899-4260

Michael Lombardo
Essex County
County Administrator
mlombardo@essex-virginia.org
804-443-4331

Roy M. Gladding
Town of Tappahannock
Mayor
rgladding@tappahannockva.gov

Eric Pollitt
Town of Tappahannock
Town Manager
epollitt@tappahannock-va.gov
804-443-3336





US 17/360 (Tappahannock Boulevard/Church Lane) Corridor Study

Thank you.

